

From: [Jump, Christine](#)
To: [SMITH, MARTIN L](#); [Michael Stephenson](#)
Subject: FW: north plant
Date: Thursday, May 08, 2014 10:54:00 AM
Attachments: [north plant.pdf](#)

NOTE: This pit on the north plant (currently debris filled) is apparently deeper than we thought. Soil samples collected near it may not have been collected deep enough to detect releases from the bottom.

Chris Jump, L.G.
Waste Remediation and Permitting Branch
US EPA, Region 7
jump.chris@epa.gov
(913) 551-7141

Mailing address: 11201 Renner Boulevard, Lenexa, KS 66219

-----Original Message-----


From: RO-2-3-AWMD-East-X7530@epa.gov [<mailto:RO-2-3-AWMD-East-X7530@epa.gov>]
Sent: Thursday, May 08, 2014 10:43 AM
To: Jump, Christine
Subject: north plant

Please open the attached document. It was scanned and sent to you using a Xerox multifunction device.

Attachment File Type: pdf, Multi-Page

multifunction device Location: RO-2.3-AWMD-East-X7530
Device Name: XRX9C934E040206

For more information on Xerox products and solutions, please visit <http://www.xerox.com>



#10

Name & Location: **REID Supply**
WICHITA KS
 Date & Time: **4-5-84**
 Photographer: **Bundy**
 Camera Setting: **Auto**

Caption: **DRUMS OF CAUSTIC**
WASH MATERIAL

#11

Name & Location: **REID Supply**
WICHITA KS
 Date & Time: **4-5-84**
 Photographer: **Bundy**
 Camera Setting: **Auto**

Caption: **EVAPORATION PIT —**
CONDENSOR WATER

#12

Name & Location: **REID Supply**
WICHITA KS
 Date & Time: **4-5-84**
 Photographer: **Bundy**
 Camera Setting: **Auto**

Caption: **EVAPORATION PIT —**
CONDENSOR WATER

Name & Location: **REID Supply**
WICHITA KS
 Date & Time: **4-5-84**
 Photographer: **Bundy**
 Camera Setting: **Auto**
 Caption: **DRUMS - REAR OF**
NORTH PLANT

#13

Name & Location: **REID Supply**
WICHITA KS
 Date & Time: **4-5-84**
 Photographer: **Bundy**
 Camera Setting: **Auto**
 Caption: **DRUMS - REAR OF**
NORTH PLANT

#14